

# 000 «Полимер Экспорт» ПРОМЫШЛЕННЫЕ ЛАКОКРАСОЧНЫЕ ПОКРЫТИЯ naum-profie.ru 28 (4932)773-503

Release date: 1.10.2024 Manufacturer: Russian Federation ТУ 20.30.22-002-69372620-2020

# **Primer EPPEX BS**

CERTIFICATE	State Registration Certificate № RU.01.PA.02.008.E Declaration of Conformance POCC RU Д-RU. PA01 System including primer «Eppex» and enamel «Poly Khotkovo-Test», LLC NPO «LKP» to confirm project It is included in the system CTO-01393674-007-2019 painting". MSDS №69372620-20-24550 от 17.10.2024 г. MSDS № 69372620-20.30-3128 от 12.03.2021 г.	. B.09510/24 от 12.03.2024 г. /tex» undergone accelerated env ted lifetime of the coating – 20 yea	ars
DESCRIPTION	Two component epoxy primer for steel and concrete surfaces.		
FIELDS OF APPLICATION	EPPEX BS primer based on zinc phosphate pigments with high anti-corrosion efficiency is used as a primer or interlayer coating in systems subjected to mechanical and / or chemical exposure. It is suitable both for anticorrosive treatment of new metal structures and for refinishing work. Thick-layer application is possible in one operation. The material can also be used as a primer layer for concrete surfaces anticorrosive coatings. It is used as a primer or intermediate layer for coating materials on an epoxy and polyurethane basis in complex protection systems, as well as an independent coating used inside premises or under a roof. Due to its high chemical resistance, hardness and resistance to abrasive wear, the primer is good for carrying out anti-corrosion work on diverse industrial facilities. It is used to paint the internal surfaces of tanks for storing industrial water, dark petroleum products and mineral fertilizers; to protect steel surfaces, including bridges, vehicles, cranes, steel masts, conveyors, etc. Information on the material resistance to various media is available on request. Main fields of application: oil and gas industry, power engineering, mechanical engineering, transport construction.		
TECHNICAL DATA	Colour	Grey, reddish-brown, other colo	ours - due to customer need
	Gloss	Matt	
	Mana fraction of dry residue component A		ur)
	Mass fraction of dry residue component A       70±5% (depending on the colour)         Adhesion to metal (GOST 15140), no more       1 point		
		i point	
	Density component A	1,35±0,15 g/cm <sup>3</sup>	
	Density components A+B	1,30±0,15 g/cm <sup>3</sup>	
	Max. one layer thickness, viscosity 25 s	400 microns wet layer	
	Dry volume residue	54±3%	
	Dry film thickness and estimated consumption	Dry film thickness, microns	Estimated consumption, g/m <sup>2</sup>
	min	80	193
	max	300	722
	Hardener	EPPEX BS	
	Due to the wide range in color and / or gloss, this description is informative. Certificate of quality is the document confirming the quality of each production lot.		
INSTRUCTION FOR USE	Metal surface should be abrasive blasted to grade 1 or 2 due to GOST 9.402 (Sa 2^(1/2) or Sa 2 to ISO 8501- 1:2007). Cleaned surface must be free of dust and grease. If the quality of surface preparation decreases, the service life and its operating performance may change.		
CONDITIONS	Two component epoxy primer EPPEX BS is applied +35°C and relative humidity no more 80%. Surface temperature should be 3° higher than dew p		ture from +5ºC to



POACTRO









# ООО «Полимер Экспорт» ПРОМЫШЛЕННЫЕ ЛАКОКРАСОЧНЫЕ ПОКРЫТИЯ 28 (4932)773-503 8 (4932)773-503

APPLICATION		
	Blending	The product is two components. Component A is a dispersion of pigments and anticorrosion filler in epoxy resin. Component B is a hardener solution. Mix the contents of the containers in the supplied proportions. After mixing, use within the specified pot life. <u>Mixing sequence:</u> The basis (component A) is mixed with a construction mixer. Then mixed hardener (component B) is added to the basis (component A) and thoroughly mixed with a construction mixer. <b>Attention!</b> Careless mixing or incorrect ratio can lead to uneven curing and painting film properties weakening.
	Proportions	100:13 by weight 5,5:1 by volume
	Pot life at 20⁰C, no less	5 hours
	Air-free spraying	Thinning: 0-20% Nozzle diameter: 0,011-0,017" Initial pressure: 120-180 atm
	Air spraying	Operation viscosity:18-60 s Thinning: 10-35% Nozzle diameter:1,4-2,5 mm Initial pressure: 3,0-4,0 atm
	Cross linking at 20⁰C	No less than 1,5 hours
	Brush, roller	Can be recommended for small and hard-to-reach areas. Thin the primer depending on the working conditions when using brush.
	Thinner	Formula thinner EPPEX
	Cleaner	Formula thinner EPPEX, thinners of type P4, P5.
	Finishing	Tubing, pistol and other spraying tools must be cleaned after using.
	Cleaning	Wash the tools after using immediately. The frequency of washing depends on the amount of sprayed material, the temperature and the time since the shutdown, including any time lag.

#### DRYING TIME

Surface temperature Degree 1 (GOST 19007)	<b>+5°С</b> 4,5 ч	<b>+10°С</b> З ч	<b>+20°С</b> 2 ч	<b>+30°С</b> 1 ч 10 м
Degree 3 (GOST 19007)	10 ч	8 ч	4 ч	3 ч
Minimum recoating interval	12 ч	4 <b>u</b>	1,5 ч	1ч
Start of operation	20 д	14 д	7д	7д

*Minimum recoating interval*: the minimum recommended time the next coat to be applied. *Start of operation*: the minimum time the coating to be exposed to a given environment.

These data should be considered only as indicative for a wet film thickness of 100 microns.

## PACKAGE SIZE

Metal euro bucket 21 l: basis 21 kg Metal bottle 3 l: hardener 2,8 kg

### STORAGE

Store in a tightly closed container in a dry room at a temperature from -40 °C to +40 °C, away from sources of ignition, protecting from direct sunlight and moisture.











## 000 «Полимер Экспорт» ПРОМЫШЛЕННЫЕ ЛАКОКРАСОЧНЫЕ ПОКРЫТИЯ naum-profie.ru **2 8 (4932)773-503**

GUARANTED STORAGE LIFE	Expire date is 24 months in case if delivery and storing rules are followed. After expire date shouldn't be used without tests.
HEALTH AND SAFETY	When painting work, use personal protective equipment (respirators, gloves, glasses, etc.). Work inside the room should be carried out with artificial (local, general) or natural ventilation. Use the primer only in places without sources of open fire and ignition. Avoid contact with skin or eyes. In case of skin contact immediately wipe with a rag or cotton swab, rinse thoroughly with soapy water, do not use solvents. In case of eyes contact rinse with clean water for at least 10 minutes, consult a doctor. In case of ingestion, consult a doctor.

## RECYCLING

Packing materials are recycled as consumer waste.

#### Further Information.

The recommendations above are based on our own research and our best knowledge but don't fully guarantee any particular case as it depends on the quality, friability and porosity of the base. The local working conditions and methods may vary and are beyond our control. Therefore we cannot be held responsible for the actual work on the site. The information is currently updating.



Собственное

современное



